

Evans-Eadom, Nailah

From: Nakamura, LisaMarie
Sent: Thursday, August 14, 2014 3:49 PM
To: R10-SERVICE CENTER Mail Group
Subject: Hot water not flowing on the 17th floor

Both bathrooms and CID sink in Processing room. When hot water lever is turned there is nothing. Cold water lever flows very low.

Best Regards,

Lisa Marie Nakamura
Administrative Specialist
US Environmental Protection Agency
Criminal Investigation Division
Seattle Area Office
1200 Sixth Ave. STE 900
Seattle, WA 98101
(206) 553-0511 Direct
(206) 553-0300 Fax

WARNING: The information contained herein may include **LAW ENFORCEMENT SENSITIVE** (LES) and/or information protected by the provisions of the PRIVACY ACT, the further distribution of which (beyond the recipients to whom it has been addressed) may be in violation of federal security information regulations, civil and/or criminal laws, without having first received the expressed written consent to release or further disseminate this material by U.S. EPA CID. If you are not the intended recipient, please contact the sender by reply email AND completely destroy all copies of the original email, message and attachments.